
FiberLinX Hardware Addendum

Default Jumper Correction

In the chart on page 2.2 of the enclosed manual, the default settings shown for Dip switches 1 and 2 (factory set) for 1300 mm/PLUS modules are wrong. On such modules, switches 1 and 2 should both be set to OFF.

1000 Park Drive • Lawrence, PA 15055-1018 USA

TEL: (724) 746-5500 • FAX: (724) 746-0746

www.blackbox.com

© 1999 Black Box. All rights reserved.

The information in this document is subject to change without notice. Black Box assumes no responsibility for any errors that may appear in this document. *FiberLinX* is a trademark of the manufacturer. Other brands or product names may be trademarks and are the property of their respective companies.

Document Number 50-84111BB-00 A0

October 1999
