

Dear Customers,

The Configuration DIP Switch SW-1 and SW-2 for the MD1980C modem card hardware version P1 are reversed. When you configure the options and operating parameters of your modem, please refer to the user's guide for the description of each switch and the location for SW-1 and SW-2 as shown in this attached diagram.

