

# Firmware revision information for:

## ServSwitch CX Uno IP

### Version 1.4

Original shipping release.

### Version 1.5

*January 2009*

SVN: 674+

1. Support for video mode 1920x1200 @ 60Hz over local port added (default DDC EDID changed).
- 2) Support for Sun key creation using hotkeys on non-Sun style keyboards (need to be enabled using OSD option).
- 3) Various fixes for keyboard occasionally repeating or losing characters in very rare circumstances.
4. Logging off local port does not work when using a PS/2 to USB converter – issue fixed.
5. New support processor image for improved mouse handling.
6. Adding too much text to the kvm port field in a host entry corrupts OSD display – issue fixed.
7. Keyboard typematic repeat does not work with PS2 dongle to a windows PC – issue fixed.
8. Orange OSD status not correct in all cases – issue fixed.
9. OSD Screensaver can kick in if typing continuously – issue fixed.

10. Hotkeys + up, Hotkeys + down have unanticipated behavior – issue fixed.
11. Feature request added: allow the use of HOME and END keys in OSD.
12. Unit reports a cascaded switch as an "unknown dongle" – fixed.
13. Bug fix to prevent host list display type being reset by cascade changes.
14. Feature request added - private and video only modes from the OSD.

## **Version 1.6**

*March 2009*

SVN: 851

Update release to fix specific issues:

1. Fixes bug associated with DHCP failing to get an address and using a static IP address on startup.
2. Avoids the internal filing system becoming fragmented and unusable due to excessive log messages. This bug could cause a kind of “slow rusting” of the integrity of the product’s internal operating system over a long time. On a typical system this would start to cause operational problems after an estimated 10 years of use. For a system that renews its DHCP leases every few tens of seconds, this could lead to operational problems after a few weeks due to some bugs associated with the DHCP allocation system. The upgrade also enables products that have become unusable due to excessive log messages to be brought back to full operation.
3. Handling of AltGraphic modified keys – bug fixed.
4. Support added for 1920 x 1080 half width mode.
5. When entering an IP default gateway the validity of the gateway is now checked.